





EXISTING CONDITIONS



PHOTO #1









The site is composed of several residential lots and the New Life Mennonite Church. Old Rt.108 and the adjacent concrete retaining wall will remain with improvements to serve as a buffer between Clarksville Pike and the propoded community.



PHOTO #5



PHOTO #6



PHOTO #7











Street Lighting



Hightower Willow Oak



Red Maple October Glory



Bloodgood London Plane Tree



River Birch



White Oak



Virginia Sweetspire "Henry's Garnet"



Dwarf Southern Magnolia



Limelight Hydrangea



Inkberry Holly



Otto Luyken Cherry Laurel



Korean Spice Virburnum



Garden Walls



Site Landscape Walls







